



# Axles

**SERVICE BULLETIN**  
**29.12.2000**

**No. S10007**

Page 1/1

## **TEMPORARY INPUT SHAFT SEAL IN FRDP-13/16, FSDP-14, SRDP-30 & SSDP-12 AXLES**

During the period from 4 January 2000 to 6 April 2000 (Axle S/N 00064 to 01182) Sisu Axles used an input shaft oil seal that was smaller in outside diameter due to a shortage of the standard oil seal. To accommodate the smaller diameter, a spacer ring was installed in the carrier housing.

When replacing the smaller input shaft oil seal, remove the spacer ring and use the standard oil seal (P/N 91122-08504).

Sisu Axles, Inc.  
Customer Support  
Autotehtaan tie 1  
PL 189  
13101 Hämeenlinna  
Phone +358 204 55 2999  
Fax +358 204 55 2900