



CHANGE IN THE OIL FILLING PLUG IN THE TRIDEM DRIVE GEAR FP-330

Change: The upper oil filling/inspection plug has been removed and the lower oil filling/inspection plug has been moved approximately 5 mm downward. There are no changes in part numbers.

Cause of change: This change is to better control the correct amount of oil.

Oil Level: Oil quantities for the different axle mounting positions when the oil is at the level of the plug opening are as follows (approx.):

Axle Angle	Oil Quantity
0°	18.0 ltrs
1°	19.5 ltrs
2°	21.0 ltrs
3°	22.5 ltrs

Identify: In the new design there is only one oil filling/inspection plug compared to two in the old design.

Changed Parts:

Description	Old design	New design
Plug 90871-22193	2 pcs	1 pcs
Seal ring 91201-22150	2 pcs	1 pcs

Interchangeability: The new design is totally interchangeable with the old design.

Date of change: From serial No. 00951, March 2000.